

形EE-SX47/67

アンプ内蔵フォト・マイクロセンサ

取扱説明書

このたびは、本製品をお買い上げいただきまして、まことにありがとうございます。ご使用に際しては、次の内容をお守りください。

- 電気の知識を有する専門家がお取り扱いください。
- この取扱説明書をよくお読みになり、十分にご理解のうえ、正しくご使用ください。
- この取扱説明書はいつでも参考できるよう大切に保管してください。



* 4 0 1 8 7 0 7 - 8 F *

オムロン株式会社

© OMRON Corporation 2008-2022 All Rights Reserved.

安全上の注意

●警告表示の意味

△警告

正しい取り扱いをしなければ、この危険のために、軽傷・中程度の傷害を負ったり、万一の場合には重傷や死亡にいたる恐れがあります。また、同様に重大な物的損害を受ける恐れがあります。

△警告

安全を確保する目的で直接的または間接的に人体を検出する用途に本製品は使用できません。人体保護用の検出装置として本製品を使用しないでください。

安全上の要点

●電源電圧について

仕様電圧範囲を超えて使用しないでください。仕様電圧範囲以上の電圧を印加したり、交流電源を印加すると、破裂したり焼損する恐れがあります。

●誤配線について

電源の極性など誤配線をしてください。破裂したり、焼損する恐れがあります。

●負荷について

負荷を短絡させないでください(電源に接続しないでください)。破裂したり、焼損したりする恐れがあります。

本センサの保護構造はIP50(IEC60529準拠)であり防水・防塵構造となっています。水や油等液体が本体に付着するアプリケーションでは使用しないでください。

本製品の廃棄時は産業廃棄物として廃棄ください。

使用上の注意

定格を超える周囲雰囲気、環境では使用しないでください。

●取りつけ時

端子に直接はんだ付けをして使用の場合は下表の範囲でお使いください。はんだ付け条件

	温度	許容時間	備考
こて	350°C以下	3s以下	はんだ付けは端子根元より1.5mm以上離してください。

Model EE-SX47/67

Compact Pre-wired Photomicrosensor with Amplifier (Non-modulated)

INSTRUCTION SHEET

Thank you for selecting OMRON product. This sheet primarily describes precautions required in installing and operating the product.

Before operating the product, read the sheet thoroughly to acquire sufficient knowledge of the product. For your convenience, keep the sheet at your disposal.

TRACEABILITY INFORMATION:

Representative in EU:
Manufacturer:
Omron Europe B.V.
Wegalaan 67-69
2132 JD Hoofddorp,
The Netherlands
Shikoku Honkawa, Shimogyo-ku,
Kyoto 600-8530 JAPAN
Ayabe Factory
3-2 Narutani, Nakayama-cho,
Ayabe-shi, Kyoto 623-0105 JAPAN

Notice:
In a residential environment, this product may cause radio interference, in which case the user may be required to take adequate measures.

© OMRON Corporation 2008-2022 All Rights Reserved.

PRECAUTIONS ON SAFETY

●Meanings of Signal Words

WARNING Indicates a potentially hazardous situation which, if not avoided, will result in minor or moderate injury, or may result in serious injury or death. Additionally there may be significant property damage.

WARNING This product is not designed to be used either directly or indirectly in applications that detect human presence for the purpose of maintaining safety. Do not use this product in sensing devices designed to provide human safety.

PRECAUTIONS FOR SAFE USE

• Power Supply Voltage
Do not exceed the voltage range indicated in the specifications. Applying a voltage exceeding the specifications or using an AC power supply may result in rupture or burning.

• Faulty Wiring
Do not reverse the power supply polarity. Doing so may result in rupture or burning.

• Load
Do not short-circuit the load. (Do not connect to the power supply.) Doing so may result in rupture or burning. Be sure to install a protection, such as a fuse. (Fusing current 0.1A) to the wiring for the load. The sensor has no load short protection function.

• These Photomicrosensors have an IP50 (conforms to IEC60529) enclosure and do not have a water-proof or dust-proof structure. Therefore, do not use them in applications in which the sensor will be subjected to splashes from water, oil, or any other liquid.

• Liquid entering the Sensor may result in malfunction.

• Dispose of this product as industrial waste.

PRECAUTIONS FOR CORRECT USE

Make sure that this product is used within the rated ambient environmental conditions.

● Installation

When direct soldering to the terminals, use the following guidelines.

Soldering Conditions

Item	Temperature	Permissible time	Remarks
Soldering iron	350°C max.	3s max.	The portion between the base of the terminals and the position 1.5 mm from the terminal base must not be soldered.

・端子保持部はポリカーボネートを使用しているため上記ははんだ付け条件を超えてお使いにならないと、端子保持部が熱変形・製品は機器上支障をきたすことがあります。
・形EE-SX-SYで始まる直流光方式のフォトマイクロセンサは機器内蔵用のため、特別な外乱光対策は施していません。直流光方式のセンサを白熱灯下などの外乱光の影響があるところでは、外乱光の影響を避けるために設置してください。
・センサの取りつけの際は、刃のない車いすつ側部に確実につけてください。
・フォトマイクロセンサをねじ締めつけで固定する場合は、M3ねじをご使用ください(ねじの緩み防止のためネジ座金を合せてお使いください)。そのときの締めつけ強度は0.59N·m以下にしてください。
注:締めつけ強度は、機種により異なりますので、各商品個別の注意事項をご覧ください。
・センサの検出部に物が衝突しないようにして下さい。検出面などに傷がつると特性劣化になります。
・振動・衝撃などで取りつけのゆるみ、ガタなどが生じていないか確認の上、使用してください。


●配線時

<未使用的出力線の処置について>


使用しない出力線は、必ず絶縁処理をしてください。

<サージ対策について>

電源ラインにサージがある場合、使用環境に応じてツェナーダイオードZD(30~35V)やコンデンサ(0.1~1μF)などを接続し、サージが消えることを確認した上で使用してください。



リレーなどの小型誘導負荷を駆動する際は下図のように配線してください。(このとき、逆電圧吸収用のダイオードを必ず接続してください。)



高圧線、動力線とフォトマイクロセンサの配線が同一配管、あるいはダクトで行われると、誘導を受けることにより、誤動作や、破損の原因となる場合もありますので、別配線、または単独配管してください。

コネクタ(専用)を装着するときは、ロックが確実にかかったことを確認してください。

EE-1006, EE-1010シリーズのコネクタケーブルをご使用になる際に、L端子(②桃色)線を使用しない場合は、ノイズの影響を受ける可能性がありますので、未使用的L端子線をコネクタ根元から切断し、絶縁テープを巻くなどの端子と接触しないよう処理してください。

<負荷短絡保護について>

この機種は、負荷短絡保護機能を備えています。負荷短絡などが生じた場合は出力がOFF状態となりますので配線を見直したうえで電源を再投入してください。短絡保護回路がヒットされます。また負荷短絡保護は定格負荷電流以上の電流が流れますと動作します。C負荷を使用される場合は突入電流が定格負荷電流以下のものをご使用ください。

●その他

・電源印加中におけるコネクタの脱着は避けてください。破損の原因になります。

・次のような取りつけ場所は、誤動作や故障の原因となりますので使用しないでください。

① 鹿埃やオイルミストの多い場所

② 腐食性ガスの多い場所

③ 水、油、薬品が直接および間接的に飛散する場所

④ 屋外または、太陽光などの強い光があたる場所

・使用時の周囲温度は定格で定められた範囲内で使用してください。

・有機溶剤、アルカリ、芳香族炭化水素、塩化脂肪族炭化水素がセンサにかかると、溶解や特性劣化を招くことがありますので、これらの薬品がセンサにかかるないようにして下さい。

・本製品に接続する電源ケーブルは10m未満にしてください。

・電源環境などの影響で電源投入時に出力パルスが発生する場合があります。ご使用の際には、電源投入より100ms経過後の安定した検出可能状態でご使用ください。

・ご使用の際には、電源投入より100ms経過後の安定した検出可能状態でご使用ください。

* The terminal base uses a polycarbonate resin, which could be deformed by excessive soldering heat, resulting in damage to the product's functionality.
* The Sensors without light modulation (i.e., EE-SX, EE-SY) are built into the device being used and are, therefore, not equipped to deal with interference from an external light source. When using a Sensor without light modulation in an area exposed to an incandescent light or other external light interference, install so as to minimize the effects of external light sources.
* Mount the Sensors securely on a flat surface.
* Mount the Sensor with two M3 screws, using a spring washer to ensure the screws will not become loose. Use a tightening force of 6 kgf-cm (0.59 N·m) max. Note: Be sure to read the precautions for the model being used before tightening the screws.
* Install so that nothing can collide with the sensing section of the Sensor. Damage to the sensing surface will result in inferior performance.
* Before using the Sensor, check to be sure that it has not become loose due to vibration or shock.


●Wiring

<Unused Output Lines>


Be sure to isolate output lines that are not going to be used.

<Countermeasures Against Surge>

If there is surge in the power supply, try connecting a capacitor (with a capacitance of 0.1 to 1 μF) or a Zener diode (ZD in the diagram below, with a rated voltage of 30 to 35 V). Use the Sensor only after confirming that the surge has been removed.



When driving a small inductive load, such as a relay, wire as shown below. (Be sure to connect a diode to absorb the reverse voltage.)



If Photomicrosensor wires are placed in the same tubes or ducts as high-voltage lines or power lines, induction may be received and may result in faulty operation or burning. Either wire the Photomicrosensor separately or place the wires in separate tubes.

Make sure that the connectors (either dedicated or commercially available) are securely locked.

When using EE-1006 and EE-1010 series connectors and/or cables without using the L terminal (②: pink) line, they may be affected by noise. Be sure to take measures such as cutting the unused L terminal line from the root of the connector and wrapping the insulating tape to avoid them from contacting other terminals.

<Load short circuit protection>

This product is provided with function of load short circuit protection. Control output turns off when this function operates. After checking of wiring and load current, make power supply again. Then the circuit is reset. Load short circuit protection operates when the current is more than the rated load current. The inrush current should be less than the rated load current when C load is used.

●Other Precautions

・Do not disconnect the Connector from the Sensor when power is supplied to the Sensor, or Sensor damage could result.

・Do not install the Sensor in the following places to prevent malfunction or trouble:

1. Places exposed to dust or oil mist

2. Places exposed to corrosive gas

3. Places directly or indirectly exposed to water, oil, or chemicals

4. Outdoor or places exposed to intensive light, such as direct sunlight

・Be sure to use the Sensor under the rated ambient temperature.

・The Sensor may be dissolved by exposure to organic solvents, acids, alkali, or aromatic hydrocarbons, causing deterioration in characteristics. Do not expose the Sensor to such chemicals.

・For power cable connecting to this product, use the cable of less than 10m in length.

・Function of this sensor will be stable 100ms after turning on the power supply.

Make sure that this product is used within the rated ambient environmental conditions.

● Installation

When direct soldering to the terminals, use the following guidelines.

Soldering Conditions

• Power Supply Voltage
Do not exceed the voltage range indicated in the specifications. Applying a voltage exceeding the specifications or using an AC power supply may result in rupture or burning.

• Faulty Wiring
Do not reverse the power supply polarity. Doing so may result in rupture or burning.

• Load
Do not short-circuit the load. (Do not connect to the power supply.) Doing so may result in rupture or burning. Be sure to install a protection, such as a fuse. (Fusing current 0.1A) to the wiring for the load. The sensor has no load short protection function.

• These Photomicrosensors have an IP50 (conforms to IEC60529) enclosure and do not have a water-proof or dust-proof structure. Therefore, do not use them in applications in which the sensor will be subjected to splashes from water, oil, or any other liquid.

